



HRVATSKI HIDROGRAFSKI INSTITUT

**ADRIATIC SEA PILOT**  
**Volume II**

SUMMARY OF CORRECTIONS  
October 2024

## **SUMMARY OF CORRECTIONS**

This Summary of Corrections is an integral part of the publication Adriatic Sea Pilot, Volume II, Sedmovraće to Rt Oštra, 2021.

It includes all corrections in force up to and including NTM 9/2024, cancelling all previous Summaries of Corrections. Authorised distributors shall enclose this Summary of Corrections with the publication Adriatic Sea Pilot, Volume II, Sedmovraće to Rt Oštra, 2021.

**ADRIATIC SEA PILOT**  
**Volume II**  
Sedmovračé to Rt Oštra

**p. 37**

22 - 3/23 IMPORTANT MARITIME REGULATIONS: ports

For: The ports open to international maritime traffic (seasonal border crossing...) are as follows (...) seven days before the beginning of Holidays.

Read: Permanent border crossing ports of entry for international passenger traffic in maritime transport are as follows: Umag, Pula, Mali Lošinj, Vis, Ubli, and Cavtat.

**p. 39**

46 - 8/21 IMPORTANT MARITIME REGULATIONS, PILOTAGE: working channel

Pilotage, Replace:

For: ...and pilot companies on VHF channel 12.

Read: ...and pilot companies on VHF channel 8.

**p. 40**

23 - 12/22 IMPORTANT MARITIME REGULATIONS, PILOTAGE: coastal pilotage

Delete the existing text concerning coastal pilotage and replace it with the following:

Coastal pilotage means pilotage in a part of the internal waters and the territorial sea up to the limit of port pilotage.

Vessels of 40 000 GT and greater, except vessels without cargo which have a gas free certificate or a cargo tank inerting certificate issued by an authorised company, shall be subject to compulsory coastal pilotage as follows:

1. vessels carrying noxious liquid substances in bulk as laid down in Annex II to the MARPOL Convention,
2. vessels carrying liquified gas,
3. oil tankers,

being conducted:

1. for the purpose of entering the ports open to international traffic:

- a) for Rijeka port: from position 44°56.2'N – 14°13.0'E up to the limit of port pilotage
- b) for Zadar port: from position 44°23.3'N – 14°34.6'E up to the limit of port pilotage
- c) for Šibenik port: from position 43°38.7'N – 15°52.3'E up to the limit of port pilotage
- d) for Split port: from position 43°28.2'N – 16°01.0'E up to the limit of port pilotage
- e) for Ploče port: from position 43°05.0'N – 17°00.0'E up to the limit of port pilotage.

2. when operating between ports open to international traffic from the position of port pilot disembarkation in the port of departure to the position of port pilot embarkation in the port of arrival.

Coastal pilotage is compulsory for all vessels of 500 GT and greater, for the purpose of entering the ports open to international traffic Plomin and Bršica, from position 44°56.0'N – 14°06.6'E up to the limit of port pilotage.

Coastal pilotage is compulsory for all vessels of 500 GT and greater, and all yachts of 1000 GT and greater, navigating in the area of Tihi Kanal, which forms part of the sea area between the line connecting Rt Oštro (Kraljevica) – rt Šilo (Krk island) to N, and the parallel 45°13'N to S. Pilot embarks from N in position 45°15.0'N – 14°31.0'E, and from S in position 45°9.9'N – 14°40.8'E.

Coastal pilotage is compulsory for all vessels of 500 GT and greater, and all yachts of 1000 GT and greater, navigating in the area of Fažanski Kanal, which forms part of the sea area between the line connecting Rt Martulin (mainland) – Rt Glavina (Mali Brijun) to N, and the line connecting Rt Proština (mainland) – S end of Sv. Jerolim island – Rt Peneda (Veliki Brijun) to S. Pilot embarks from N in position 44°56.7'N – 13°46.0'E, and from S in position 44°52.3'N – 13°46.9'E.

Coastal pilotage is compulsory for all vessels of 500 GT and greater, and all yachts of 1000 GT and greater, navigating in the area of Sedmovračé, which forms part of the sea area between the line connecting Rt Bonaster (Molat) – Lagnići islet – Rt Veli rat (Dugi Otok) and the line connecting Stopanji Rt – Kamenjak islet – Rt Križ (Sestrunj) – Jidula islet – Rt Sv. Petar (Ugljan), except ships in the public coastal regular service. Pilot embarks from N in position 44°12.6'N – 14°56.3'E, and from S in position 44°11.5'N – 14°50.0'E.

**p. 40**

30 - 9/22 IMPORTANT MARITIME REGULATIONS, PILOTAGE: Pilotage services in ports

Zadar – city port, Zadar – Gaženica, replace the existing text as follows:

Zadar – city port (including dangerous cargo)

Pilotage service is available 24 hours a day. Pilot embarkation/disembarkation: 44°07.8'N – 015°10.8'E.

The position is intended for pilot embarkation:

a) for all ships over 500 GT and yachts over 1000 GT which plan to berth at city port Zadar

b) for ships over 500 GT carrying dangerous cargo.

Zadar – Gaženica (excluding dangerous cargo)

Pilot embarkation/disembarkation: 44°06.2'N – 015°12.7'E

The position is intended for pilot embarkation for all ships over 500 GT and yachts over 1000 GT which plan to berth at passenger or cargo harbour Gaženica except ships carrying dangerous cargo.

**p. 40**

30 - 4/22 IMPORTANT MARITIME REGULATIONS, PILOTAGE: Pilotage services in ports

After paragraph Zadar – Gaženica, Insert new paragraph:

Zadar – county and local ports opened for public transport under the authority of the Harbour Master's Office Zadar.

Pilot embarkation/disembarkation: 0.5 M prior to entering the port area.

**p. 41**

34 - 7/22 REGULATIONS APPERTAINING TO NAVIGATION IN PASSAGES, STRAITS AND RIVERS, AND AREAS OF PROHIBITED NAVIGATION: Passage to Šibenik harbour

In the existing text, Replace:

For: ...or 10 min before leaving the Šibenik harbour. Any vessel which intends to stop in the channel must inform the Centre about that

Read: ...or 10 min before leaving the Šibenik harbour. Vessel that starts navigation from a berth or another place in the channel must also request permission to continue navigation via VHF radio-telephone on the VHF radio channel of the VTS sector (ch 09). If the vessel is planning to stay in the channel awhile, he is obliged to inform the Center about it, and the latter has the responsibility to inform both Harbour Master Office Šibenik and the VTS service on the VHF radio channel of the VTS sector (ch 09).

**p. 42**

35 - 7/22 REGULATIONS APPERTAINING TO NAVIGATION IN PASSAGES, STRAITS AND RIVERS, AND AREAS OF PROHIBITED NAVIGATION: Passage through Pašmanski tjesnac

In the existing text, Replace:

For: ...even when proceeding NW, if they transmit safety message (securite) on VHF...

Read: ...even when proceeding NW, with permission of the VTS service and if they transmit safety message (securite) on VHF...

**p. 43**

36 - 7/22 REGULATIONS APPERTAINING TO NAVIGATION IN PASSAGES, STRAITS AND RIVERS, AND AREAS OF PROHIBITED NAVIGATION: Prohibited navigation in Unijski Kanal and Kanal Krušija and parts of Srednji Kanal, Murtersko More and Žirjanskog kanal

Insert:

8. Exceptionally, vessels referred to point 1 of this chapter of less than 6000 GT, which come to marine farms for the purpose of loading/unloading cargo (fish) or supplying marine farms, may navigate in the area referred to in point 2, if pilot embarked.

**p. 48**

18 - 1/23 ARRIVAL AND STAY OF FOREIGN YACHTS AND BOATS: text replacement

For: The ports of entry (with permanent border crossing) are as follows [...] seven days before the beginning of Holidays.

Read: Permanent border crossing ports of entry for international passenger traffic in maritime transport are as follows:

Umag, Pula, Mali Lošinj, Vis, Ubli, and Cavtat.

**p. 61**

33 - 10/20 ARCHIPELAGO OF ZADAR: marine farms

Marine farms, Replace:

For: ...Ugljan island (Svitla bay - Rt Japlenički)...

Read: ...Ugljan island (Svitla bay - Rt Japlenički, wider sea area of approach to Lamjana Mala and Lamjana Vela inlets)...

**p. 64**

35 - 10/20 SAKARUN, bay: light

Landmarks, Replace by:

Landmarks: Light with obscured sector on Rt Lopata - red tower with gallery; reddish causeway on a hillside at the head of the bay.

**p. 69**

28(T) - 6/19 LUKA, bay: works

Caution, Insert:

Luka bay is closed to all traffic due to works.

**p. 71**

39 - 12/23 SALI, harbour: landmarks

Landmarks, Replace the existing text with the following:

Landmarks: Belfry in the village; white-red aerial mast above the harbour; light on the head of the outer breakwater – green tower with column and gallery; light on the head of the inner breakwater – red tower with column and gallery.

**p. 71**

40 - 12/23 SALI, harbour: berth

Berth, Replace the existing text with the following:

Berth: Boats can berth stern-to W shore, from the inner breakwater with depths of about 1.4 m. Vessels may berth in N part of the harbour alongside a quay used by fishing boats of the canning factory; part between the first three bollards is used by ferry. It is also possible to berth alongside inner sides of the outer and inner breakwater; in Saščica cove NW of Rt Bluda to a quay in front of the hotel settlement, with depths of about 4 m.

**p. 73**

21 - 10/21 RIVANJSKI KANAL, channel: light

Landmarks, Replace:

For: ...islets of Paranak Veli and Paranak Mali in SE part of the channel, close off the SE coast of Sestrunj island.

Read: ...islets of Paranak Veli, marked by light - red tower with gallery, and Paranak Mali lying close off the SE coast of Sestrunj island.

**p. 91**

37 - 7/22

BLITVENICA, above-water rock: ODAS plutača

After introductory text, insert:

S of Hridi Blitvenica, in 43°35,89'N – 015°34,19'E (WGS 84) ODAS lighted buoy is established.

**p. 97**

15(T) - 1/20 NORTHEASTERN COAST OF UGLJAN ISLAND: works

After introductory text insert:

Caution: Batalaža harbour is closed to all traffic.

**p. 106**

16 - 10/23 ZADAR, harbour: Berth

Berth, Delete:

Berthing is prohibited to all vessels at the main pier, Obala Kralja Petra Krešimira IV.

**p. 109**

48(T) - 7/21 SUKOŠAN, harbour: works

Caution, Add:

Sukošan harbour is partially closed due to construction works.

**p. 109**

41(T) - 12/23 PAŠMANSKI KANAL, channel: works

Caution, Insert:

Construction works are in progress on the new lighted mark on Planac islet, W of Biograd n/M. The area of works is marked by a yellow lighted buoy.

**p. 111**

29(T) - 6/19 MRLJANE, harbour: shipwreck

Caution, Insert:

The use of harbour is restricted because of a shipwreck.

**p. 112**

25 - 1/22 TKON, harbour: light

Landmarks, Replace:

For: ...light on the breakwater head - red tower with column and gallery; light on the ferry pier - white tower with column and gallery.

Read: ...light on the N breakwater head - green column; light on the S breakwater head - red tower with column and gallery; light on the ferry pier - white tower with column and gallery.

**p. 113**

48 - 7/20 SV. FILIP I JAKOV, harbour: new light

Landmarks, Replace:

For: Light on Kočerka shoal - green tower with column and gallery on concrete base in the sea.

Read: Light on Kočerka shoal - green tower with column and gallery on concrete base in the sea; light on the breakwater head – green tower with column and gallery.

**p. 113**

27(T) - 4/23 SV. FILIP I JAKOV, harbour: works

Caution, Insert:

Until October 2024, works are in progress in Sv. Filip i Jakov harbour. The area of works is marked by lighted buoys (special mark). The harbour is closed to all traffic.

**p. 115**

5(T) - 5/20 PAKOŠTANE, harbour: works

Caution, Insert:

Until 22 April 2022 the E part of Drage harbour (Dugovača) is closed.

**p. 119**

24(T) - 11/23 MAINLAND COAST FROM PAKOŠTANE TO RT PLOČA AND THE ŠIBENIK ISLANDS: works in Vrgadski Kanal

After introductory text, Insert:

Caution: Works are in progress on underwater power cable replacement in Vrgadski kanal (between Drage and Vrgada island).

**p. 120**

33 - 1/24 DUGOVAČA, bay: Landmarks

After introductory text, Insert:

Landmarks: Light on the marina breakwater head – green column NE of Glavina cape.

**p. 123**

22(T) - 1/24 MARINA HRAMINA: caution

After introductory text, Insert:

Caution: A pair of lighted buoys have been established on the approach route to Marina Hramina NW of breakwater. The buoys mark the area of works in the marina.

**p. 130**

28 - 12/20 SV. ANDRIJA, inlet: light

Caution, Replace:

For: ...marked by a concrete cylindrical spar beacon...

Read: ...marked by a light - concrete cylindrical tower with column (yellow with black horizontal band) and topmark...

**p. 132/133**

22 - 2/23 VODICE and MARINA VODICE: Regulations

Regulations, Replace:

For: From 2 July to...

Read: From 1 July to...

**p. 134**

17 - 7/23 KANAL SV. ANTE, channel: Caution

After paragraph Regulations, Insert new paragraph:

Caution: NE of Rt Baba and E of Rt Južni Turan (E entrance to the channel) there are lighted ODAS buoys.

**p. 138**

34 - 6/24 VRNAŽA, boat harbour: Landmarks

Landmarks, Replace:

For: ...marina complex on the peninsula of Mandalina on the S side; light on the head of N breakwater...

Read: ...marina complex on the peninsula of Mandalina on the S side; light on the head of the floating breakwater – green column; light on the head of N breakwater...

**p. 145**

17 - 8/22 KAPRIJE, harbour: new light

Landmarks, Replace:

For: Light on the pier head – white tower with column and gallery.

Read: Light on the head of ferry pier at the harbour entrance – white tower with column and gallery; light on the pier head – white tower with column and gallery.

**p. 145**

18 - 8/22 KAPRIJE, harbour: new light

Berth, Replace:

For: At two piers; the head of larger pier is used by ferry.

Read: Ferry pier situated at the harbour entrance is used by ferry. Boats can berth at two piers.

**p. 148**

25(T) - 11/23 ŠIBENSKI KANAL, channel: works

After introductory text, Insert:

Caution: Construction works and pipeline laying operations are in progress between mainland and Prvić island. Works are carried out using several vessels. Caution and wide berth are requested.

**p. 151**

37 - 6/24 KRAPANJ, boat harbour: Caution

Caution, Replace the existing text with the following:

From Rt Grmine towards SSE extends a wide shoal with a minimum depth of 1.7 metres. South of that depth there is a lighted mark – column on base in the sea (yellow above black) with topmark – two black cones points downward (S cardinal). Southeast of this shallow area there is a shoal with above-water rock Kraplun, marked by a yellow lighted buoy (special mark), and the island of Krapanj.

Northwest of above-water rock Kraplun, extends Krapanj shoal. Its N/NW edge is marked by two lateral lighted marks – red column on base in the sea.

**p. 155**

33 - 12/21 LUKA ROGOZNICA, bay: landmarks

Landmarks, Replace the existing text with the new text:

Hill Movar (120 m); lighthouse Mulo - stone tower and dwelling; signal pillar buoy on Veli Brak shoal NNW of Hrid Mulo, coloured black with red horizontal band and topmark - two black spheres one above the other (isolated danger); signal beacon on base in the sea W of Smokvica Mala islet - black column with red horizontal bands and topmark - two black spheres one above the other (isolated danger); light on Rt Gradina (N entrance point) - red square tower; light on Rt Konj (S entrance point) - green tower with column and gallery; light on the above-water rock Kalebinjak in the passage between the mainland and the islet of Smokvica Vela - tower with column and gallery coloured black with red horizontal bands and topmark - two black spheres one above the other (isolated danger).

**p. 156**

16 - 3/24 ROGOZNICA, harbour: landmarks

Landmarks, Replace:

For: ...light on S corner of the quay – green tower with column and gallery.

Read: ...light on S corner of the quay – green tower with column and gallery; lighted mark W of Hrid Školjić rock – green pillar on base in the sea.

**p. 157**

17 - 3/24 MARINA FRAPA: landmarks

Landmarks, Replace:

For: ...light on S corner of the quay – green tower with column and gallery.

Read: ...light on S corner of the quay – green tower with column and gallery; lighted mark W of Hrid Školjić rock – green pillar on base in the sea.

**p. 164**

42 - 12/23 TROGIRSKI ZALJEV, bay: landmarks

Landmarks, Replace:

For: ...in the W group, the steep islet of Kluda...

Read: ... in the W group, the above-water rock Vela Sika, marked by a light – green pillar on base in the sea, the steep islet of Kluda...

**p. 166**

31 - 4/21 TROGIRSKI KANAL, channel: landmarks

Landmarks, Replace:

For: ...belfries in the town; lateral light buoys...

Read: ...belfries in the town; light on the breakwater head in Brigi-Lokvice boat harbour - green tower with gallery; lateral light buoys...

**p. 166**

43(T) - 8/18 TROGIRSKI KANAL, channel: caution

Insert new paragraph:



Caution: In the area about 200 m E and W of the bridge Mainland - Čiovo island, works are in progress that may affect the coastline. The area of works is marked by yellow buoys. This area was not surveyed after the completion of the bridge, and changes in the hydrography may occur.

**p. 166**

11 - 9/23 TROGIRSKI KANAL, channel: directions

Directions, Replace:

For: ...near Kamerlengo tower to port hand side. When approaching from E...

Read: ... near Kamerlengo tower to port hand side. The best point of passage under the bridge is marked by a day mark, and during the night by lighted marks on both sides of the bridge. When approaching from E...

**p. 169**

19 - 6/21 KAŠTELANSKI ZALJEV, bay, Divulje harbour: restricted navigation area

Regulations, Replace:

For: Navigation, fishing and stopping are prohibited ...

Read: Navigation, fishing and stopping are prohibited to all vessels, except naval vessels, in a sea area between the coast off Divulje harbour and a line joining the following approximate points at sea: Rt Taršće, cape - 1 cable S off Divulje harbour breakwater head - 3.5 cables WSW off the Divulje harbour breakwater head.

**p. 169**

17 - 11/21 KAŠTELANSKI ZALJEV, bay: ODAS buoy

Caution, delete the existing text:

- yellow oceanographic buoy with topmark (special mark) established about 1 mile NW of the light on Rt Marjan;

**p. 170**

24 - 5/23 KAŠTEL STARI, boat harbour: new paragraph

After paragraph KAŠTEL NOVI, Insert:

KAŠTEL STARI, boat harbour

(43°32,96'N – 16°20,67'E)

Charts: 100-21; MK-16; Plan 47

Situated on the northern coast of Kaštelanski Zaljev, about 0.2 mile east of Kaštel Novi.

Landmarks: Light on the head of S breakwater – green tower with column and gallery; light on the head of N breakwater – red tower with column and gallery.

Weather: Vessels at berth are safe in any wind and sea. Berth on the outer side of breakwater are exposed to winds and waves from II and III quadrants.

Berth: Vessels are secured stern-to piers and quay, and on the outer side of breakwater. Boat harbour is used by local craft.

**p. 173**

18 - 7/23 SPLIT, harbour: Regulations

After paragraph Cables and pipelines, Insert new paragraph:

Regulations: In the area of Split harbour, anchoring is prohibited except for the safety of the ship. Anchoring and berthing of vessels are prohibited in the area of Split harbour, from the concession boundary of the Matejuška boat harbour in the west to the small pier in the east (situated approximately in the middle of the seaside promenade Riva).

**p. 175**

18(T) - 3/24 Zenta, yacht harbour: caution

Caution, Insert:

Construction works are in progress on the underwater outfall in Trstenik cove, E of the breakwater root in Zenta harbour to the south towards the open sea, 400 metres in length. Navigation is prohibited in a radius of 0.1 mile from the area of works.

**p. 180**

28(T) - 3/23 MILNA, harbour: works

Caution, Insert:

Works are in progress on the quay in Racić area (N coast of the harbour); the area of works is marked by buoys. Caution and wide berth requested.

**p. 181**

50(T) - 8/21 BRAČKI KANAL, channel: waverider buoy

After introductory text insert:

Caution: Waverider buoy has been established in 43°29.1'N - 016°27.8'E (WGS 84). Navigation is prohibited in a radius of 200 metres from the buoy.

**p. 181**

30(T) - 6/22 BRAČKI KANAL, channel: waverider buoy

After introductory text insert:

Caution: Waverider buoy has been established in 43°29,34'N – 016°27,68'E (WGS 84). Navigation is prohibited in a radius of 100 metres from the buoy.

**p. 184**

25 - 5/23 POSTIRA, harbour: landmarks

Landmarks, Replace:

For: ...light on the breakwater head – square stone tower...

Read: ...light on the head of the quay in front of the hotel; light on the breakwater head – square stone tower...

**p. 184**

19 - 8/22 PUČIŠĆA, harbour: submarine power cable

After paragraph Weather insert new paragraph:

Cables and pipelines: Submarine power cable is laid from 43°21.0'N – 016°44.5'E to the opposite coast in 43°21.1'N – 016°44.8'E.

**p. 185**

18 - 11/21 POVLJA, harbour: wreck

Caution, delete the existing text:

Landing to NE shore is prohibited on account of a dangerous wreck in the vicinity of 43°20.12'N - 16°50.15'E.

**p. 188**

19(T) - 11/21 OMIŠ, harbour: works

Caution, Insert:

Until further notice, works are in progress in Omiš harbour. The work area is marked by lighted buoys (special mark).

**p. 205**

31 - 6/22 MIDDLE AND SOUTH DALMATIAN COAST AND ADJACENT CHANNELS: ODAS buoy

After Marine farms, Insert:

Caution: In Vis Channel, in 43°08,78'N – 016°06,75'E (WGS 84) ODAS lighted buoy is established.

**p. 209**

35(T) - 11/20 KOMIŽA, harbour: works

Caution, Insert:

Underwater works are in progress in the area of Komiža bay.

**p. 209**

23 - 2/23 KOMIŽA, harbour: anchorage

Anchorage, Replace:

For: NW and S of the quay to mooring floats; about 850 m S of the light on breakwater head in depths of about 30 m; the bottom is sand.

Read: NW and S of the quay to mooring floats.

**p. 211**

32 - 6/22 PALAGRUŽA ISLAND: ODAS buoy

Caution, Insert:

NE of Palagruža island, in 42°29,38'N – 016°24,08'E (WGS 84) ODAS lighted buoy is established.

**p. 218**

39 - 7/22 SUĆURAJ, harbour: new light, orientation

Instead of existing paragraph Landmarks, insert:

Landmarks: Light on Rt Sućuraj - square stone tower and dwelling; light on the head of the ferry pier - white tower with column and gallery; light on the breakwater head - red tower with column and gallery.

**p. 218**

40 - 7/22 SUĆURAJ, harbour: berth

At the end of text under Berth, insert:

Immediately close to breakwater root, pier of the outern ferry berth is situated. It is possible to approach and berth on either side of the ferry pier.

**p. 219**

24(T) - 12/22 WESTERN AND NORTHERN COASTS OF KORČULA ISLAND: Caution

After introductory text, Insert:

Caution: Construction works are in progress in Polačište harbour. The area of works is marked by yellow lighted buoys (special mark).

**p. 219**

27 - 11/23 VELA LUKA, harbour: landmarks

Landmarks, Replace:

For: ...light on Rt Vranac – pyramidal stone tower with red gallery; light on the head of ferry pier – white tower...

Read: ...light on Rt Vranac – pyramidal stone tower with red gallery; light on W corner of the ferry pier located on S side of the harbour entrance – green tower with column and gallery; light on the pier head in the harbour – white tower...

**p. 219**

28 - 11/23 VELA LUKA, harbour: berth

Berth, Replace:

For: The quay in the ferry terminal N of the shipyard in W part of the harbour is reserved for ferries; the coast NW of the shipyard to the quay of the former canning factory at the harbour entrance is reserved for local craft.

Read: The ferry terminal with three berths on S side of the harbour entrance is reserved for ferries. The berthing mole N of the shipyard in W part of the harbour is also used by ferries; the coast NW of the shipyard is used by local craft.

**p. 219**

12 - 9/23 PLOČICA ISLET: isolated danger lighted mark

Caution, Insert:

About 350 metres ESE of Pločica islet there is a lighted mark – black column with red horizontal bands on base in the sea with topmark – two black spheres one above the other (isolated danger).

**p. 219**

33 - 4/22 VELA LUKA, harbour: landmarks

Landmarks, Replace:

For: ...light on Kamenjak islet – stone tower; wooded islet of Ošjak; light on Rt Vranac...

Read: ...light on Kamenjak islet – stone tower; light on NW edge of Ošjak islet – green tower with gallery on concrete block; light on Rt Vranac...

**str. 221**

30 - 9/21 KNEŽA, bay: depth

Caution, Replace:

For: In the passage between the islet of Kneža Vela and Rt Kneže depth is 4 m...

Read: In the passage between the islet of Kneža Vela and Rt Kneže depth is 3.9 m...

**p. 224**

31 - 9/21 EASTERN COAST OF KORČULA ISLAND: toponym, depth

In the introductory text, amend toponyms Stupe Vele and Stupe Male to Stupa Vela and Stupa Mala.

Caution, Replace:

For: - unmarked shoal Križ (4 m)...

Read: - unmarked shoal Križ (4.9 m)...

For: - shoal (2.5 m) extending to 200 m offshore NE of Rt Soline...

Read: - shoal (3 m) extending to 200 m offshore NE of Rt Soline...

For: - rock Krastovica in the passage...

Read: - above-water rock Krastovica in the passage...

For: - low, bare above-water rock Knežić...

Read: - islet Knežić...

For: ...the islets of Stupe Vele and Stupe Male (in the obscured sector of the light on Stupe Vele islet)...

Read: ...the islets of Stupa Vela and Stupa Mala (in the obscured sector of the light on Stupa Vela islet)...

For: - unmarked dangerous rock Gojak SW...

Read: - unmarked dangerous rock Gojak (1.9 m) SW...

**p. 225**

32 - 9/21 KANAL JEŽEVICA: depth, toponym

Directions, Replace:

For: ...care is necessary to avoid the shoal Križ (4.5 m)...

Read: ...care is necessary to avoid the shoal Križ (4.9 m)...

For: ...between the islet of Planjak and the unmarked rock and shoal Krastovica...

Read: ...between the islet of Planjak and the above-water rock and shoal Krastovica...

**p. 225**

33 - 9/21 DOMINČE, harbour: depth

Directions, Replace:

For: ...care is necessary to avoid Križ shoal (4.5 m)...

Read: ...care is necessary to avoid Križ shoal (4.9 m)...

**p. 225**

17 - 11/22 MARINA LUMBARDA: Landmarks

Landmarks, Replace:

For: ...green light buoy (lateral starboard hand) at the marina entrance...

Read: ...green lighted mark (lateral starboard hand) at the marina entrance...

**p. 225**

19 - 11/22 MARINA LUMBARDA: Caution

Caution, Replace the existing text with:

Caution: Care is necessary to avoid the shoal Bad (1.6 m) about 90 m NW of the light on breakwater.

**p. 231**

41(T) - 7/22 PLOČE, harbour: works

After paragraph Weather, insert new paragraph:

Caution: Works are in progress in approach channel of Ploče harbour. For free approach contact Port authority on VHF channel 16 and 9. Wide berth and reduced speed requested.

**p. 231**

16(T) - 2/24 PLOČE, harbour: waverider buoy

After paragraph Weather, insert new paragraph:

Caution: Lighted waverider buoy is established in 43°00'34.8"N – 017°23'28.8"E. Navigation is prohibited in a radius of 100 metres from the buoy.

**p. 231**

34 - 12/21 NERETVA RIVER: landmarks

Landmarks, Replace:

For: ...light on S mole head - green hut with column...

Read: ...light on S mole head - white hut with green horizontal band on the top and a small green column...

**p. 231**

58(T) - 4/19 NERETVA RIVER: works

Caution, Insert:

Reconstruction works are in progress on the right bank of the river near Komin. Caution and reduced speed are requested.

**p. 231**

26(T) - 5/23 NERETVA RIVER: archaeological research

Caution, Insert:

Underwater archaeological research is in progress in Komin area. Wide berth and reduced speed are requested.

**p. 237**

35 - 4/22 KANAL MALOG STONA, bridge Mainland – Pelješac: landmarks

Landmarks, Replace the existing text as follows:

Bridge Mainland – Pelješac with approach lateral lighted buoys with topmark, lighted and signal marks on the bridge (lateral marks and best point of passage marks); light on Rt Blaca – white tower with column and gallery on base; light on Rt Rep Kleka – white tower with gallery.

**p. 237**

36 - 4/22 KANAL MALOG STONA, bridge Mainland – Pelješac: directions

After paragraph Caution, Insert new paragraph:

Directions: When approaching from Neretvanski Kanal, the bridge connecting Mainland – Pelješac is prominent.

Approximately in the middle of the line joining Rt Međed (mainland) – Rt Blaca (Pelješac), a navigational corridor has been established, marked by lateral lighted buoys with topmark, lateral lighted marks on the bridge, and best point of passage marks. Vertical clearance under the bridge, in the middle of the navigational corridor is 55 m and width is 200 m. When approaching from W, the track leads between two pairs of lighted lateral buoys: approach buoy no. 1 – green lighted buoy with topmark; approach buoy no. 2 – red lighted buoy with topmark; approach buoy no. 3 – green lighted buoy with topmark; approach buoy no. 4 – red lighted buoy with topmark.

After passing these buoys, it is necessary to steer for mid-passage under the bridge, marked by two pairs of lateral lighted marks and by the best point of passage lighted mark.

After passing the bridge, the track leads between the last two pairs of lateral lighted buoys: approach buoy no. 5 – green lighted buoy with topmark; approach buoy no. 6 – red lighted buoy with topmark; approach buoy no. 7 – green lighted buoy with topmark; approach buoy no. 8 – red lighted buoy with topmark.

During daylight, signal marks marking the navigational corridor are located on the front of the bridge (W and E side): lateral mark (starboard hand) – green triangle point upwards; lateral mark (port hand) – red square; best point of passage – circle with red and white vertical stripes.

**p. 238**

19 - 10/23 ZALJEV MALOG STONA, inlet: Caution

Caution, delete:

The area of construction works on the Mainland – Pelješac bridge is marked by lateral light buoys.

**p. 245**

18(T) - 6/23

UBLI, harbour: construction works

After paragraph Weather, Insert new paragraph:

Caution: The area of works in Ubli harbour is marked by four yellow lighted buoys (special mark). Navigation is prohibited within the construction area, between the buoys and the coast.

**p. 256**

50(T) - 7/20 POMENA, bay: buoy

Caution, Insert:

When approaching Pomena bay from the S side of Galicija rock, care is necessary to avoid a yellow measurement buoy.

**p. 269**

21 - 7/23 STONSKI KANAL, inlet: landmarks

Landmarks, Replace:

For: ...town of Ston at the head of inlet N of the harbour; fairway from Broce harbour to Ston harbour marked on N by four green lights, and on S by four red lights (towers on bases in the sea); red light on the pier head in Broce harbour.

Read: ...town of Ston at the head of inlet N of the harbour; Ston bridge which connects two shores of Stonski Kanal inlet; fairway from Broce harbour to Ston harbour marked on N by six green lights, and on S by five red lights, red light on the pier head in Broce harbour, white light on the bridge above Stonski Kanal inlet, and red light on the pier head in Ston harbour.

**p. 269**

21 - 6/23

STON, harbour: landmarks

Landmarks, Replace:

For: ...above the village; green lighted marks...

Read: ...above the village; bridge across Stonski Kanal inlet marked by a white isophase light; green lighted marks...

**p. 269**

15 - 4/24 STONSKI KANAL, inlet: Directions

After paragraph Anchorage, Insert:

Directions: Due to an underwater stone slab at the entrance to the navigational channel, around 80 metres NNW (on the opposite coast of the channel) of the light on the pier head in Broce harbour, the track leads closer to that light. After passing the first pair of approach lighted marks E of the pier in Broce harbour, the track leads between the second pair of lighted marks, then between the pair of lighted buoys under the bridge. Thence the track leads closer to the red lighted mark NW of the bridge, keeping to the middle of the channel, and then, after the last pair of lighted marks it is necessary to steer towards the head of the quay in Ston harbour, from which a light is exhibited – red tower, leaving two green lighted marks to starboard.

The best point of passage under the bridge is marked by a white isophase light on both sides of the bridge above Stonski Kanal channel, and by a day mark – circle with red and white vertical stripes.

Vertical clearance under the bridge at that spot is 33 m.

**p. 270**

23 - 7/23 STON, harbour: directions

Directions, Replace the existing text with the following:

To avoid a submerged obstruction in the fairway entrance, about 80 m NNW of the light on pier head in Broce harbour (on the opposite shore), the track leads closer to that light. The fairway from Broce harbour to Ston harbour is marked on N by six green lights, and on S by five red lights, red light on the pier head in Broce harbour, white light on the bridge across Stonski Kanal inlet and red light on the pier head in Ston harbour.

The best point of passage under the bridge is marked by a white isophase light on both sides of the bridge which connects two shores in Stonski Kanal inlet.

Passing the first pair of approach light beacons E of the pier in Broce harbour, the track leads between the second pair of light beacons, then between the pair of lighted buoys under the bridge, and after that the course should be taken closer

to the red light beacon NW of the bridge, keeping closer to mid-channel. From the last pair of light beacons it is necessary to steer for the head of the quay in Ston harbour from which a light is exhibited – red tower, leaving two green beacons to starboard.

Vessels entering the channel must wait at Broce harbour to give precedence to a vessel leaving. Vessels must not leave Ston harbour until a vessel already in the channel enters the harbour.

**p. 273**

43 - 12/23 RIJEKA DUBROVAČKA, inlet: historic wreck

Regulations, Insert:

Anchoring and underwater activities are prohibited in the sea area E of Batahovina quay bounded by a circle with 100 metres radius.

**p. 274**

44 - 12/23 BATAHOVINA, quay: historic wreck

After Berth, Insert:

Regulations: Anchoring and underwater activities are prohibited in the sea area E of Batahovina quay bounded by a circle with 100 metres radius.

**p. 279**

31(T) - 4/23 MAINLAND COAST FROM DUBROVNIK HARBOUR TO RT SUSTJEPAN: Sv. Andrija islet, waverider buoy

After introductory text, Insert:

Caution: Lighted waverider buoy has been established in position 42°38'44"N – 017°58'18"E (E of Sv. Andrija islet).

Navigation is prohibited in a radius of 200 metres from the buoy.

**p. 280**

23 - 6/23

MLINI, harbour: new light

Landmarks, Replace:

For: Belfry E of...

Read: Light on the breakwater head – green column; belfry E of...

**p. 282**

35 - 6/22 MAINLAND COAST FROM RT SUSTJEPAN TO RT OŠTRA: ODAS buoy

Caution, insert:

SW of Molunat, in 42°23,65'N – 018°21,53'E (WGS 84) ODAS lighted buoy is established.

**p. 281**

24 - 1/24 CAVTAT, harbour: landmarks

Landmarks, Replace:

For: ...and gallery; hotel buildings; belfry with clock.

Read: ...and gallery; light on the head of W pier – red tower with column and gallery; light on the pier head – white tower with column and gallery.