



HRVATSKI HIDROGRAFSKI INSTITUT

ADRIATIC SEA PILOT
Volume II

SUMMARY OF CORRECTIONS

JULY 2021



SUMMARY OF CORRECTIONS

Summary of corrections is an integral part of publication Adriatic Sea Pilot, Volume II, Sedmovraće to Rt Oštra.

It includes all corrections in force up to and including NTM 6/2021, and cancels all previous Summaries of Corrections.

Authorised distributors should enclose this Summary of Corrections with the above mentioned publication.

ADRIATIC SEA PILOT
VOLUME II
Sedmovraće to Rt Oštra

33 - 10/20 ARCHIPELAGO OF ZADAR: marine farms

Marine farms, Replace:

For: ...Ugljan island (Svitla bay - Rt Japlenički)...

Read: ...Ugljan island (Svitla bay - Rt Japlenički, wider sea area of approach to Lamjana Mala and Lamjana Vela inlets)...

p. 61

35 - 10/20 SAKARUN, bay: light

Landmarks, Replace by:

Landmarks: Light with obscured sector on Rt Lopata - red tower with gallery; reddish causeway on a hillside at the head of the bay.

p. 64

28(T) - 6/19 LUKA, bay: works

Caution, Insert:

Luka bay is closed to all traffic due to works.

p. 69

30(T) - 4/21 SREDNJI KANAL, channel: caution

Caution, Insert:

Until 15 July 2021, works are in progress on the marine farm. Wide berth is requested.

p. 72

15(T) - 1/20 NORTHEASTERN COAST OF UGLJAN ISLAND: works

After introductory text insert:

Caution: Batalaža harbour is closed to all traffic.

p. 97

26(T) - 8/20 GAŽENICA - CARGO, FERRY, AND PASSENGER PORT: works

After introductory text insert:

Caution: Until 27 January 2022 the fishery harbour is closed to all traffic due to construction works.

p. 107

29(T) - 6/19 MRLJANE, harbour: shipwreck

Caution, Insert:

The use of harbour is restricted because of a shipwreck.

p. 111

54(T) - 4/19 TKON, harbour: works

Insert new paragraph:

Caution: Until 19 August 2021 the W part of the harbour is closed to maritime traffic.

p. 112

48 - 7/20 SV. FILIP I JAKOV, harbour: new light

Landmarks, Replace:

For: Light on Kočerka shoal - green tower with column and gallery on concrete base in the sea.

Read: Light on Kočerka shoal - green tower with column and gallery on concrete base in the sea; light on the breakwater head - green tower with column and gallery.

p. 113

5(T) - 5/20 PAKOŠTANE, harbour: works

Caution, Insert:

Until 22 April 2022 the E part of Drage harbour (Dugovača) is closed.

p. 115

28 - 12/20 SV. ANDRIJA, inlet: light

Caution, Replace:

For: ...marked by a concrete cylindrical spar beacon...

Read: ...marked by a light - concrete cylindrical tower with column (yellow with black horizontal band) and topmark...

p. 130

31 - 4/21 TROGIRSKI KANAL, channel: landmarks

Landmarks, Replace:

For: ...belfries in the town; lateral light buoys...

Read: ...belfries in the town; light on the breakwater head in Brigi-Lokvice boat harbour - green tower with gallery; lateral light buoys...

p. 166

43(T) - 8/18 TROGIRSKI KANAL, channel: caution

Insert new paragraph:

Caution: In the area about 200 m E and W of the bridge Mainland - Čiovo island, works are in progress that may affect the coastline. The area of works is marked by yellow buoys. This area was not surveyed after the completion of the bridge, and changes in the hydrography may occur.

p. 166

19 - 6/21 KAŠTELANSKI ZALJEV, bay, Divulje harbour: restricted navigation area

Regulations, Replace:

For: Navigation, fishing and stopping are prohibited ...

Read: Navigation, fishing and stopping are prohibited to all vessels, except naval vessels, in a sea area between the coast off Divulje harbour and a line joining the following approximate points at sea: Rt Taršće, cape - 1 cable S off Divulje harbour breakwater head - 3.5 cables WSW off the Divulje harbour breakwater head.

p. 169

35(T) - 11/20 KOMIŽA, harbour: works

Caution, Insert:

Underwater works are in progress in the area of Komiza bay.

p. 209

18(T) - 11/16 VELA LUKA, harbour: underwater works

Insert new paragraph:

Caution: Until further notice, underwater works are in progress within the lines joining the following positions:

a) 42°57'38.08"N - 016°42'11.54"E

b) 42°57'37.74"N - 016°42'15.44"E

c) 42°57'37.37"N - 016°42'19.35"E

d) 42°57'36.99"N - 016°42'23.31"E

e) 42°57'34.22"N - 016°42'27.87"E.

Navigation and all activities are prohibited in the above-mentioned area.

p. 219

36(T) - 11/20 KORČULA, harbour: works

Insert new paragraph:

Caution: Reconstruction works are in progress on the breakwater on the W coast in Korčula harbour.

p. 223

58(T) - 4/19 NERETVA RIVER: works

Caution, Insert:

Reconstruction works are in progress on the right bank of the river near Komin. Caution and reduced speed are requested.

p. 231

19(T)- 1/19 KANAL MALOG STONA, channel: works

Caution, Insert:

Construction works are in progress on the Mainland - Pelješac bridge, approximately on the line joining Rt Međed (mainland) - Rt Blaca (Pelješac). The area of works is marked by light buoys (special mark).

Navigable corridor, marked by lateral light buoys, has been established within the area of works. Fixing of piles in the seabed is underway. Wide berth is requested.

p. 237

50(T) - 8/18 ZALJEV MALOG STONA, inlet: light buoys, works

Caution, Insert:

Light buoys have been established approximately on the line joining Rt Međed (mainland) - Rt Blaca (Pelješac), marking the area of construction works on the Mainland - Pelješac bridge. When approaching the area, the track leads between green and red light buoys which are closer to the mainland coast (Rt Međed).

p. 238

50(T) - 7/20 POMENA, bay: buoy

Caution, Insert:

When approaching Pomena bay from the S side of Galicija rock, care is necessary to avoid a yellow measurement buoy.

p. 256

52(T) - 8/18 KOLOČEPSKI KANAL, channel: Sv. Andrija islet, waverider buoy

Insert new paragraph:

Caution: Lighted waverider buoy has been established in position 42°38'44"N - 017°58'18"E (characteristic Fl(5)Y 20s 4M).

Navigation is prohibited in a radius of 200 metres from the buoy.

p. 261

40(T) - 10/20 DONJE ČELO, bay: works

Insert new paragraph:

Caution: Reconstruction works on the quay are marked by yellow signal buoys.

p. 267